BREEZESUITE™ 8.2 Service Pack 2 Release & Installation Notice

This software is a Service Pack for BreezeSuite™ cardiorespiratory diagnostic software version 8.2 and is intended to be installed on any computer that has BreezeSuite 8.2 already installed. BreezeSuite 8.2 Service Pack 2 can be installed on workstations, but not on BreezeSuite Servers. Service Pack 2 includes any changes that were in Service Pack 1.

Minimum System Requirements

- BreezeSuite cardiorespiratory diagnostic software version 8.2

Warning: Installing Service Pack 2 over BreezeSuite software version 8.2 will over-write the translation files.

NOTE: For multiuser installations, Service Pack 2 is only applied to workstations. Service Pack 2 is not applied to the BreezeSuite Multiuser™ Server installation.

INSTALLATION

1. Close all applications.
2. Insert CD into CD Drive. (If downloaded from the MGC Diagnostics website, extract/unzip the BreezeSuite82SP2.zip file and select BreezeSuite82SP2.exe.)
3. Wait for the installation to start automatically (~15 seconds) or run the BreezeSuite82SP1.exe file on the CD.
4. After the software unzips the files it will begin to install the extracted files to your hard drive.
5. After the files have been copied remove the CD.

LANGUAGE TRANSLATIONS

Service Pack 2 has been translated into: French, German, Italian, Spanish, Portuguese, Polish and Russian.

1. Follow the Installation Instructions above before proceeding.
2. With the Service Pack 1 CD in the CD Drive, browse to the **Translations** folder on the CD.
3. If the files were downloaded from the MGC Diagnostics website, browse to the **Translations** folder of the file that was extracted.
4. Double click on the appropriate language executable file.
5. At the “Location To Save Files” screen select **Next**.
6. At the “Overwrite Protection” screen select **Yes To All**.
7. After the files have been extracted and copied select **Finish**.

BreezeSuite is a trademark of Medical Graphics Corporation.

Changes for Service Pack 1

- Addresses communication issues with Mortara X-Scribe software interface "ECG Only" testing in Ultima CardiO_2 configurations

Changes for Service Pack 2

- Corrected an intermittent issue where the treadmill would go to 0.5 mph instead of zero when users click on the "Stop Treadmill" button.
- Improved the speed of SUM file creation when exporting the SUM file, thus eliminating Instrument Manager errors.

BreezeSuite is a trademark of Medical Graphics Corporation.