BREEZESUITE™ 8.3 Service Pack 2 Release & Installation Notice

This software is a Service Pack for BreezeSuite™ cardiorespiratory diagnostic software version 8.3 and is intended to be installed on any computer that has BreezeSuite 8.3 already installed. BreezeSuite 8.3 Service Pack 2 can be installed on workstations, but not on BreezeSuite Servers.

Minimum System Requirements

- BreezeSuite cardiorespiratory diagnostic software version 8.3

Warning: Installing Service Pack 2 over BreezeSuite software version 8.3 will over-write the translation files.

NOTE: For multiuser installations, Service Pack 2 is only applied to workstations. Service Pack 2 is not applied to the BreezeSuite Multiuser™ Server installation.

INSTALLATION

1. Close all applications.
2. Place the USB Flash Drive into the computer. Using Windows Explorer, browse to the USB Flash Drive. If downloaded from the MGC Diagnostics website, extract/unzip the BreezeSuite83SP1.zip file.
3. Double click on the BreezeSuite83SP2.exe file on the USB Flash Drive, or from the extracted files if downloaded from the MGC Diagnostics website.
4. After the software installation is run, it will begin to install the appropriate files to your hard drive.
5. After the files have been installed, remove the USB Flash Drive from the computer if applicable.

LANGUAGE TRANSLATIONS

Service Pack 2 has been translated into: French, German, Italian, Spanish, Portuguese, Polish and Russian.

1. Follow the Installation Instructions above before proceeding.
2. With the Service Pack 2 USB Flash Drive in the computer, browse to the **Translations** folder on the USB Flash Drive.
3. If the files were downloaded from the MGC Diagnostics website, browse to the **Translations** folder of the file that was extracted.
4. Double click on the appropriate language executable file.
5. At the “Location To Save Files” screen select **Next**.
6. At the “Overwrite Protection” screen select **Yes To All**.
7. After the files have been extracted and copied select **Finish**.

BreezeSuite is a trademark of Medical Graphics Corporation.

Changes for Service Pack 1

- Added Analog IO module support for newly repackaged Ultima Series™ cardiorespiratory diagnostic systems
- Corrected issue with incorrect PF data showing on GX patients in Breeze Review
- Improved performance in calculating GX and PF predicted values
- Corrected issue with New Visit option for Orders
- Corrected issue with PDF report selection in Breeze Review
- Corrected issue with scissor valve operation
- Corrected communication issue related to Lode ergometers utilizing legacy or obsolete versions of Lode ergometer firmware/communications
- Corrected issue with DLCO calibration failing when a MIP/MEP calibration is performed prior to a DLCO calibration

Changes for Service Pack 2

- Improved communication protocol with Trackmaster 428 treadmill
- Corrected an issue in BreezeReview which caused the software to shut down when reports containing test view pages were exported after a visit was marked as Completed+Posted+Locked
- Corrected an issue where recently converted Carefusion (SensorMedics) patient files are Auto Exporting multiple visits

BreezeSuite is a trademark of Medical Graphics Corporation.